

	A	B	C	D	E	F	G	H
26								
27	FUTURE CONSIDERATIONS							
28	<i>A. The boilers will be 20 years old consideration should be give to replacement or upgrade. We hope to haave this addressed in the HVAC report due Fall 2020</i>							
29	<i>B. The building HVAC automation system currently operates on multiple systems. Gradually converting to one provider will improve the communication, response time and daily maintenance.</i>							
30	<i>C. Storm drain and pipe inlets should be inspected and replaced due to erosion.</i>							
31	<i>D. Sewer drainage is old clay and cast iron. This erodes over time.</i>							
32	<i>E. Replace Exterior doors due to corrosion from winter elements, wear & tear</i>							
33	<i>F. In an effort to increase security, it is recommended to attach the gymnasium to the main facility.</i>							
34	<i>G. Alumni Field Artificial Turf</i>							
35	<i>H. Exterior Scoreboard Replacement / Upgrade - There is currently a need to replace Alumni Field, Soccer, and Field Hockey scoreboards. We will continue to ook for funding through donations.☒</i>							